



JON M. HUNTSMAN, JR.
Governor

GARY R. HERBERT
Lieutenant Governor

State of Utah
DEPARTMENT OF NATURAL RESOURCES
Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report
Minerals Regulatory Program
08/31/2006

Supervisor _____

Mine Name: RB 1&2
Operator Name: Utah Mineral and Fossil
John Holfort
84 East 1100 North
Bountiful, Utah 84010
Inspector(s): Tom Munson
Other Participants:
Mine Status: ACT

Permit number: S0230062
Inspection Date: 08/29/2006
Time:

Weather:

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

Data base indicates this site is active but not been inspected.

Directions to Site:

Due East of the Brush Wellman mine. Hike 200 yards to site. See map.

Inspection Summary:

Site has 4-5 small pits. Disturbance is less than 0.5 acres.

Conclusions and Recommendations:

Continue to monitor site.

Inspector's Signature

Daniel Smith

Date: 8/31/2006

tm:jb

cc: John Holfort
BLM, Fillmore

Attachment: GPS & Photos

P:\GROUPS\MINERALS\WP\M023-Juab\S0230062-RB1and2\inspections\insp_08-29-2006.doc







Mine Number: S0230062
Mine Name: RB 1 and 2
Township 13 S Range 12 W Section 12 SLBM


Inspection Date Aug. 31, 2006
Map Produced by DKS

Acres Disturbed	0.5
Acres Regraded	0
Acres Seeded	0
Road Acres Disturbed	0
Total Acres Disturbed	0.5
Acres Released	0
Acres Excluded	0
Acres PreExisting	0
Acres Prelaw	0

Legend
All items symbolized in legend may not be appear on map

- County Boundary
- Township or range line: location doubtful
- Section line
- Section line: location doubtful
- Access
- Mine
- NonMine
- Reclaimed
- Other
- Interstate
- US Route
- State Route
- Primary Route
- Secondary Route
- Prelaw
- Main Dirt Road
- Unimproved Road
- Interchange
- Trail
- BLM Salable Minerals
- Community PFI
- SITLA Mineral Ownership

DOQ imagery date 1997



0 625
Feet

1:7,500 1 inch equals 625 feet
Verify Scale

Dept. of Natural Resources
Division of Oil, Gas, and Mining
Mineral Mines Program

Different data sources and input scales
may cause misalignment of data layers.
This product may not meet DOGM
standards for accuracy and content.